



BRYANT EL

2201 Havenwood Drive, Arlington, TX 76018

Scope of bond work at Bryant

- Add 2 STEM labs
- Add strings classroom
- Add secure entry vestibule
- Upgrade technology connectivity
- Identify and improve existing site accessibility
- Add additional card access controls
- Repair roof
- Repair/replace and upgrade fire alarms, heating and A/C, plumbing, interior finishes and landscaping
- Upgrade security cameras and PA system (to be done by AISD security and technology departments)

Phase	5
A/E Firm	TBD
CMAR	TBD